Workingmen's Houses, 70 Southern Avenue Dubuque Dubuque County Iowa

HABS No. IA-159-0

HABS 10WA, 31-DUBU, 14-0-

PHOTOGRAPHS HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Department of the Interior
National Park Service
Rocky Mountain Regional Office
P.O. Box 25287
Denver Colorado 80225

Workingmen's Houses, 70 Southern Avenue

HABS No. 1A-159-0

Site Location:

70 Southern Avenue

Dubuque, Oubuque County, Iowa

00T designation: Resource Site No. 1.15 Cadastral grid: NE1/4 NE1/4 S36 T89N R2E USGS quadrangle: Oubuque South Iowa 7.5' UTM coordinates: 15.692020.4706170 Lot dimensions: 39.2'x 57': .05 acre Lot description: Lots 2-1 and 2A of Lot 1 of Randall's Subdivision

Present Owner:

Iowa Oppartment of Transportation

Present Usage:

single family residence

Present Condition: good

Overall Dimensions: 1-1/2-story main block: 27'x 28'; rear addition: 6'x 11'.

Orientation:

west

Architectural Description: Plan type: rectangular: 1-1/2 stories. Foundation: concrete block perimeter walls.

Structure: wood frame

Ext. walls: permastone sheathing

Roofs

: moderately pitched, side gabled roof with shallow cross gable on the right side of the facade; 3-tab asphalt shingles throughout.

Chimneys : none Dormers : none

Windows : triple banked 8-light casements in northwest

corner of front; paired casements on northeast corner of west side; 3/1 double-hung paired on front and sides; remaining windows on first floor and those on upper floor are 1/1 cottage fixed; 3-light fixed window in cross gable on front; awning windows at basement level. All windows have slip sills, plain casings and permastone flat arch heads with keystones.

Openings

: slightly offset, single-leaf front door, with

semicircular head and permastone voussoirs;

slab door with 3 stepped lights.

Porches : concrete front and rear stoops with concrete

steps and wrought iron handrails.

Details : exposed rafters with plain fascias.

Workingmen's Houses, 70 Southern Avenue HABS No. IA-159-0 page 2

Construction Date: 1933 Architecture Style: Bungalow

Physical History: This modest bungalow was constructed in 1933, perhaps by John B. Welp. A long time occupant, Welp still lived in the house in 1970.

Significance: With its permastone exterior siding and shallowly pitched front cross gable, this house is atypical of the other workingmen's dwellings on Southern Avenue and South Locust Street but nevertheless within the mainstream of contemporary residential building trends.

References:

Sanborn Insurance Maps: 1891, 1909, 1972. Dubuque City Directories: 1925 - 1970. Dubuque County Assessment Record: 3-32-3-1.

Iowa Department of Transportation, "Draft Environmental Impact Statement - Cultural Resources Assessment."

Compiler:

Clayton B. Fraser, Fraserdesign, Loveland Colorado.

May 1988.